




Common Leakage Sites no.10

Around rooflights.




In this instance air is leaking from the outside into a warm roof area around rooflights due to inadequate or perished sealing.

Building Fabric Leakage 10: Around rooflights, including on controls and sensors for powered rooflights



10.01: Leakage found on cable to powered rooflight in main living space when flat depressurised



10.02: Thermographic image showing leakage at wood-to-wood joint in corner below rooflight